

Date: 28 April 2008

Fisher Controls R622H gas pressure regulators

Safety Notice

Fisher Controls has issued a Safety Notice regarding their R622H series gas pressure regulators, which are used as first stage LP Gas regulators.

The problem relates to gas leakage from the diaphragm flange area or from the vent opening, and will be found on initial installation or soon afterwards.

All recently installed R622H regulators should be checked. Regulators that have been factory-checked have "inspected 2008 D" indicated on the packaging. Each inspected regulator is stamped "D" on the diaphragm flange. All stock which does not have the inspection marking is to be returned to the supplier.

ESV is unaware of any incidents, but there is a potential for serious leakage, fire or explosion.

For further details contact your supplier.