

# PRODUCT SAFETY RECALL

## CUSTOMER ALERT

### **Gas Tightening Test**

Windsor Caravans advises customers that during a recent safety audit of gas fittings it was determined that there is a possibility in some circumstances of gas escaping from some fittings.

We therefore request you have your caravan/pop top inspected by a licensed gas fitter, and recommend not using your gas until inspected. The licensed gas fitter will need to contact Windsor Caravans Customer Service on 03 9930 4900 to obtain a copy of the instructions of the tests to be undertaken.

The cost of the inspection is covered under your warranty.

This notice applies to units manufactured between the 1st May 2007 and the 10th November 2008. (The date of manufacture is stamped on the VIN plate located on the chassis of the van).

Any enquiries should be directed to the  
Customer Service Manager, Windsor Caravans P/L  
on

**50 Stanley Drive Somerton, Victoria 3062**  
or telephone **03 9930 4900.**

***Windsor***  
CARAVANS