





FACT SHEET

NON-COMPLIANT USB CHARGERS, TRAVEL ADAPTORS AND POWER SUPPLIES

July 2014


Electrical safety regulators have been made aware of an increase in the supply of non-compliant USB chargers and travel adaptors following a fatality.

USB chargers and adaptors must **have** insulated pins and must **not** have holes in the pins to be compliant. All USB chargers and adaptors must be approved by an electrical testing laboratory and bear the Regulatory Compliance Mark (RCM)  or an approval number.

Non-compliant chargers	
Chargers that requires a travel adaptor	
	
No RCM or certification number	
	

Compliant chargers, travel adaptors & power supplies

Insulated pins with no holes



Approved travel adaptor with certification number



Approved power supply with RCM



**Travel adaptors & power supplies with incorrect pin configuration
Holes in pins and no insulation**

